

A
B
C
D
E
F
G
H
J
K

## 7



7


- SHOP WELD SYMBOL  
 1 WELD NO.  
 < 1 > CUTTING NO.  
 1 PT. NO.

NOTES:

1. DIMENSIONS TO BE USED AS GUIDE LINES ONLY, ALL DIMENSIONS MUST BE FIELD.
2. INSTRUMENT CONNECTIONS: SEE DETAIL 1-1 TO 1-4 ON DRAWING.
3. BRAIN CONNECTION: SEE DETAIL 1-5 ON DRAWING.
4. BALANCE PORT CONNECTION: SEE DETAIL 1-6 ON DRAWING.
5. DIMENSIONS OF THE WELD TO BE FIELD.
6. COORDINATES IN METERS, DIMENSIONS IN MM.
7. FLOW DIRECTION IS FROM "CONNECT FROM" TO "CONNECT ON".

8. SHIP WELD SYMBOLS:

	WELDING	< 1/8" CUTTING NO.		PT. NO.
---	---------	--------------------	---	---------

DRG.	SIZE	A2
ISS.	B	1 / 1
PIPELINE REFERENCE		
 浙江开山压缩机股份有限公司 Zhejiang Kaishan Compressor Co., Ltd		

FIELD  
WELD

□